

# Failure of an Embankment on Soft Clay

M. K. Yegian

Associate Professor of Civil Engineering, Northeastern University, Boston, Massachusetts

Hugo Perez Lasalvia

Teproy, Caracas, Venezuela

NOTICE: THIS MATERIAL MAY BE  
PROTECTED BY COPYRIGHT LAW  
(TITLE 17 US CODE)

**SYNOPSIS** The failure of an embankment during its construction on soft clay foundation is investigated. Field and laboratory data are used in conventional slope stability analyses to explain the cause of the failure and to evaluate the in-situ undrained shear strength of the clay which was later used in the design of the replacement dike. The results indicate that whereas the stiff embankment having a well compacted core was initially stable on the soft clay, subsequent cracking of the core due to undrained deformations reduced the shearing resistance of the dike thus, initiating the failure. The dike was eventually reconstructed in stages allowing enough time between stages for the foundation clay to consolidate and increase its shear strength. In the new dike a granular material was used in order to provide flexibility and to prevent cracking of the dike. In addition, long berms were placed on both sides of the dike to increase its stability. Field instruments including piezometers and inclinometers were used to monitor the rate of the stage construction of the new dike.

## INTRODUCTION

The site preparation for an industrial plant for producing alumina, located on the bank of the Orinoco River in Venezuela, included the construction of dikes for the purpose of creating artificial ponds where the residual material ferro-silt commonly referred to as Red Mud will be deposited. The terrain consists of two natural lagoons whose bottom elevations are about 6 meters above sea level (+6M). Hydrological records indicate that for about 8 to 9 months of the year, the Orinoco River water elevation remains higher than +6M and can be as high as +14M. Hence, for most of the year, the lagoon area remains flooded. For this reason, dikes with crest elevations of +17M were needed to prevent the flooding of the lagoons, thus creating artificial ponds which would be de-watered and then used for depositing the Red Mud.

Two and a half months after construction had started, a large section of one of the dikes, failed by sliding into the lagoon. The height of the 400 meter long dike at the time of failure was about 7 meters, (4 meters below the final design crest elevation). The dike consisted of a well compacted clay core and shell of sand, gravel and rocks. Immediate attempts made by the contractor to reshape the dike and to continue its construction resulted in similar failures in the same zone as that of the initial failure. Following these failures, extensive field and laboratory investigations were made, including; soil boring, sampling, testing and installation and monitoring of field instruments. The information obtained from this subsurface exploration program was then utilized in geotechnical engineering analysis and the causes of the failure of the dike were identified and an alternate design and construction procedure was adopted and the

dike was successfully reconstructed. The scope of this paper is limited to the presentation of the results of the subsurface soil investigation and the stability analyses made to investigate the causes of the failure of the dike. In addition, a discussion is included on the final procedures adopted for the reconstruction of the dike which is now in operation.

## SUBSURFACE INVESTIGATIONS

The subsurface investigations carried out after the failure of the dike consisted of: Field explorations and instrumentation and laboratory soil testing.

### Field Exploration and Instrumentation.

Immediately after the failure of the dike, topographical data was acquired and the extent of the failure of the dike and its shape after failure were established as shown in Figures 1 and 2. Following this, standard penetration tests were made using a sampling spoon of 2-in OD with a 140 lb. weight hammer falling 30 inches. Figures 1 and 2 show the locations of a few of the bore holes and their corresponding logs. In addition to the Standard Penetration Tests, geophysical investigations were conducted along a number of traverses and the thicknesses of different soil layers were estimated as shown in Figures 1 and 2.

Based on these field investigations and visual inspections of samples of soil retrieved from the field tests soil profiles were prepared as shown in Figures 1 and 2. In summary, the site consists of flood-plain deposit of low-to-medium plasticity silts and silty clays containing some organic matter and interrupted by layers and




Figure 1 Cross-section of Dike Prior to and After Failure




Figure 2 Subsurface Profile Along the Longitudinal Axis of Dike






Figure 4 Total Stress Stability Analyses of the Dike, Prior to Failure

dike was stable and in a way floating on its large base over the saturated clay. But, as the construction of the dike proceeded, the resulting large undrained deformations initiated the cracking of the core, thus, reducing the shearing resistance of the core and ultimately causing failure. Also, since the dike did fail (F.S. < 1.0), from the results of the stability analyses it is concluded that the undrained shear strength ratio  $S_u/\bar{\sigma}_{vo}$  for the clay should be less than 0.5.

#### After Failure.

The total stress stability analyses were repeated using the cross section of the dike after failure determined from topographical surveys. Figure 5 shows a cross section of the dike observed after failure. The stability analyses of the dike were made searching for the critical failure circle and considering a tension crack of 5 meters extending through the core. Since, after the failure, the factor of safety was greater than or equal to 1.0, from these analyses, it is concluded that the undrained shear strength ratio  $S_u/\bar{\sigma}_{vo}$  should be greater than 0.3.

In summary, the results of the stability analyses of the failed dike for conditions immediately before and after the failure indicate that the embankment material was well compacted and thus, the shear strength of the fill provided enough resistance against immediate major stability failure during the early period of its construction. However, as the dike underwent deformations due to continued undrained loading, it started to crack, thus losing shearing resistance and initiating failure. The undrained

shear strength ratio  $S_u/\bar{\sigma}_{vo}$  of the foundation clay as determined from laboratory tests was 0.25. Based on the results of these stability analyses it was concluded that this ratio determined from laboratory tests is small because of sample disturbance and is more likely to be 0.3, which agrees better with published values for similar soils. This value of  $S_u/\bar{\sigma}_{vo} = 0.3$  was later used in the analyses made for the reconstruction of the failed dike.

#### RECONSTRUCTION OF THE DIKE

For the reconstruction of the dike, alternate methods were investigated considering various constraints including: Construction timing and scheduling, required materials, cost of construction and reconstruction technique. In view of the fact that there was a delay in the completion of the alumina plant and therefore the dike would not be needed for another two years, and also the permeability of the foundation soils as indicated by the piezometers was larger than estimated in the laboratory, it was decided to adopt a stage construction procedure. By this method, the construction of the dike proceeded in stages allowing enough time between stages for the clay to consolidate and gain the required strength to achieve safety against stability failure. In addition, in order to permit construction to proceed during the "high water" seasons and to provide a flexible embankment, a granular material was used in the dike and the compacted core was eliminated. Furthermore, 13m berms were placed on both sides of the new embankment in order to provide additional stabilizing forces.




Figure 5 Total Stress Stability Analyses of the Dike After Failure

In order to predict the safe height of the dike for each stage of construction and to make estimates of the required duration in time of the different stages of loading, total stress stability analyses were made. Based on these results it was concluded that the dike could be raised to a minimum required height of +14m in time for the operation of the plant. In addition, effective stress stability analyses were made to determine the limiting pore water pressures in the foundation clay below which the dike would be safe at each stage of construction.

Prior to the construction of the dike, piezometers and inclinometers were installed within critical sections of the dike for monitoring the construction activities. Construction of the new dike started in the latter part of 1981 and by 1983 the crest elevation of the dike was brought up to +14m which was adequate for the initial phase of the operation of the plant. During each stage of construction, the piezometers were read and the data was used to monitor the rate of construction and the period between each stage. The details of the engineering analyses for the design of the new dike and the field instrument data used will be presented in a subsequent paper in the future.

#### CONCLUSIONS

The case history presented in this paper demonstrates that for embankments on soft clays, the concerns of large deformations and overall stability are interrelated. A flexible embankment having long berms is more adequate than a rigid well compacted embankment, which will invariably eventually crack if the deformations are large. The rate of construction of such an embankment is very important in controlling stability and deformations. Field instruments including piezometers and inclinometers can provide valuable information for monitoring the construction rate and identifying critical zones which would require special considerations.

The difficulties associated with the construction of embankments on soft clay foundations are well known in the geotechnical engineering profession. However, with careful field investigations, analyses and monitoring of field instruments such difficulties can be overcome and embankments can be safely constructed on soft clays.